

785000

785500

5303500



Rear layer:
Chľaba (07.2024)
opacity 100%, without izolines

17
11

5303500

5303000

Legends:

Positions of buoys are from ENC

- Red buoy
- Luminous red buoy
- Green buoy
- Luminous green buoy
- Fairway
- optimal inland waterway route
- Isoline 2,3m below LNWL
- Isoline 2,5m below LNWL
- River km mark
- Hektometer
- Border of measurement

The shallowes point of marked **fairway**: -1.43 m below LNWL2022

© Ortofotomozaika SR: „GKÚ Bratislava, NLC“, ESRI, Eurosense, Geodis, GeoEye, USGS

© Bathymetry plan: Hydromorphology department, Radovan Terek

785000

785500



SLOVENSKÝ
VODOHOSPODÁRSKY
PODNIK, štátny podnik
Povodie Dunaja, odštepny závod

Martinská 49, 821 05 Bratislava
tel.č.: 02/60 292 495
email: Hydromorfologia_BA@svp.sk

Critical sections of the Danube River Chľaba

date of measurement :	02.12.2025	gauge value :	Štúrovo 102 cm	elevation system/ reduced level:	LNWL2022
date of processing :	14.12.2025	discharge :	Štúrovo Q=1526m ³	coordinate system:	UTM 33N

sheet:
DIN-A3
rkm:
1711.5 - 1710.7
page:
23/23

