




 Rear layer:
Klížská Nemá 1 (03.2026)
opacity 100%, without isolines

- Legends:**
- Real-time position buoys**
-  - Red buoy
 -  - Luminous red buoy
 -  - Green buoy
 -  - Luminous green buoy
 -  - Fairway
 -  - Isoline 2,3m below LNWL
 -  - Isoline 2,5m below LNWL
 -  - River km mark
 -  - Hektometer
 -  - Border of measurement

 SLOVENSKÝ
VODOHOSPODÁRSKY
PODNIK, štátny podnik
Povodie Dunaja, odštepny závod

Martinská 49, 821 05 Bratislava
tel.č.: 02/60 292 495
email: Hydromorfologia_BA@svp.sk

Critical sections of the Danube River			
Klížská Nemá 1			
date of measurement :	07.09.2026	gauge value :	Gönyű -69 cm
date of processing :	19.09.2026	discharge :	Medveďov Q=m³
		elevation system/ reduced level:	LNWL2022
		coordinate system:	UTM 33N

sheet:
DIN-A3

rkm:
1792.1 - 1791.6

page:
12/24

